

## CERCLA REMOVAL ACTION DAILY WORK ORDER

## DAILY WORK ORDER

RESPONSE LOCATION (SITE NAME  
AND/OR ADDRESS AND ZIP CODE)

CONTRACT NO.

ORDER NO.

MPF Site  
E. Rutherford NJ

68-52-2101

2101-02-028

DATE

3-25-99

SHIFT

SITE/SPILL NO.

LW

EPA REGION/USDG DIST.

II

ON-SCENE COORDINATOR

PAUL KAHN

CONTRACTOR

ETI

CONTRACTOR RESPONSE MANAGER

KEVIN SHAVER

1.

N/A

MONITOR(S)

2.

DESCRIPTION OF WORK TO BE PERFORMED

1. Hold H&amp;S meeting with crew

2. Continue cleaning out sludge &amp; debris from dump #1

3. Separate sink hole in dump #1 until bottom or depth is located

4. Move T&amp;D coordinator to site

5. Begin preparations for shipping liquids on 3/26/99

NUMBER OF PERSONNEL AUTHORIZED

...1...SUPERVISORS

...1...FOREMAN

...1...OPERATORS

...7...LABORERS

...2...OTHER (SPECIFY) P.C.T. Chemist


4.

EQUIPMENT AND EXPENDABLE MATERIALS AUTHORIZED

ITEM	QUANTITY	ITEM	QUANTITY
same as previous day			

I CERTIFY THAT THE ABOVE WORK IS ORDERED AND  
AUTHORIZED BY THE CONTRACTOR IN THE PER-  
FORMANCE OF THE ABOVE CITED DELIVERY ORDER.

SIGNATURE OF OSC



I ACKNOWLEDGE RECEIPT OF THIS WORK ORDER.

SIGNATURE OF CONTRACTOR'S REPRESENTATIVE



AMENDMENTS (INCLUDE TIME AND AUTHORIZING PERSON)

SIGNATURE OF OSC

SIGNATURE OF CONTRACTOR'S REPRESENTATIVE

ORIGINAL

443065

